



## CITY OF MILPITAS

Office of Building Safety  
455 E. Calaveras Blvd.  
Milpitas, CA 95035  
408-586-3240  
[www.milpitas.gov](http://www.milpitas.gov)

**Policy:****BDP-BLG33**

Effective Date:

12/13/11

Proposed by:

BYC

Last Reviewed/  
Revised:

3/6/2023

Reviewed/  
Revised by:

JDS

Approved By:

Building Official

### GREASE DUCT ENCLOSURE

**CODE REFERENCE:**

2022 CMC – Section 510.7

**ISSUE:**

Grease duct enclosure shall be constructed of materials that can resist sustained high temperature. Gypsum panel is not a suitable material for grease duct enclosure as the Specifications for the Application and Finishing of Gypsum Panel Products GA-216 sec. 1.4 states that “Gypsum panel products shall not be used where they will be exposed to sustained temperatures of more than 125 deg F for extended periods of time.”

**POLICY:**

Grease duct enclosure shall not be constructed of gypsum panels unless the interior of the shaft enclosure is insulated to keep the temperature of the gypsum panels below 125 deg F.